

United States of America  
Department of Transportation -- Federal Aviation Administration  
**Supplemental Type Certificate**

*Number* ST02426CH-D

*This certificate issued to* Landmark Aviation  
1200 North Airport Drive  
Springfield, IL 62707

*certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.*

*Original Product - Type Certificate Number:* A46EU  
*Make:* Dassault Aviation  
*Model:* Mystere-Falcon 50

*Description of Type Design Change:*

Installation of a four place divan, in accordance with Landmark Aviation Drawing List 1012882, Revision "B", dated June 11, 2007.

*Limitations and Conditions:*

1. Compatibility of this design change with previously approved modifications must be determined by the installer.
2. Descriptive data pertaining to this design change are considered inadequate for duplication in other aircraft. This approval is limited to only the installation made in Dassault Aviation, Mystere-Falcon 50 serial number 103. This STC does not permit manufacturing of parts for multiple installations.
3. Limitations and Conditions continued on page 3.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application :* March 23, 2007

*Date of issuance:* June 22, 2007

*Date reissued :*

*Date amended :*



*By direction of the Administrator*

*Tim Winiesdorffer*  
(Signature)

Tim Winiesdorffer, DAS Administrator  
Landmark Aviation, Springfield, IL  
FAA DAS-100079-CE

(Title)



**LANDMARK**  
**A V I A T I O N**


**LANDMARK AVIATION**  
**STC PROJECT CERTIFICATION PLAN**  
**For**  
**The Installation of a 4-Place Divan**  
**In Dassault-Aviation**  
**Mystere-Falcon 50 Aircraft S/N 103**

**DAS No:** DAS-100079-CE  
**DAS Project No.:** DAS-M-674

Landmark Aviation  
Designated Alteration Station  
1200 North Airport Drive  
Springfield, IL 62707

**Doc. No.:** 1012878  
**Revision:** (B)  
**Date:** May 22, 2007

**Approved By DAS Administrator**

  
\_\_\_\_\_  
Tim Winiesdorffer

**AIRPLANE MAINTENANCE MANUAL SUPPLEMENT  
INSTRUCTIONS FOR CONTINUED AIRWORTHINESS**

**FOR**

**DASSAULT AVIATION**

**Mystere-Falcon 50 S/N 103**

**REG. # N370KP**

This supplement must be used in conjunction with the Airplane Maintenance Manuals. The information contained herein complies with FAR Part 25.1529, Instructions for Continued Airworthiness and supplements the basic Maintenance Manuals only in those areas listed, when the divan listed in this document is installed in accordance with Landmark Aviation STC number ST02426CH-D. For limitations and procedures not contained in this supplement, consult the basic Airplane Maintenance Manuals.

Accepted by:

  
*For* Robert A. Miller, DAS Administrator  
Landmark Aviation  
Springfield, IL  
DAS-100079-CE